



3301 E. Deseret Drive, St. George, UT 84790
www.wilsonelectronics.com • info@wilsonelectronics.com
phone 1-800-204-4104 • fax 1-435-656-2432

January 6, 2017

H.B. Compliance Solutions
50005 S. Ash Avenue Ste A-10
Tempe, AZ 85282

SUBJECT: Class II Permissive Change FCC ID: PWO460019

We are requesting a Class II Permissive change for our Model 460019 Signal Booster to be filed with the FCC.

Changes to the subject include additional antenna kits, and a layout change in the RF portion of the board. This includes the addition of two switches and minor placement changes in other components. No electrical, software or other changes were made. These changes will be in effect for all units.

In support of the above, the following documents have been submitted:

- Antenna Kitting
- MSCL
- MPE Exposure
- User Manual
- Test Report
- Schematic Diagram & Parts List
- Interior Images

Sincerely,

A handwritten signature in black ink, appearing to read 'Patrick Cook', written in a cursive style.

Patrick Cook

Senior Electrical Engineer