




Annex C


Out of Band Emissions



Downlink_1930 - 1990 MHz_CDMA_lower




Downlink_1930 - 1990 MHz_CDMA_upper






Downlink_1930 - 1990 MHz_GSM_lower




Downlink_1930 - 1990 MHz_GSM_upper






Downlink_1930 - 1990 MHz_WCDMA_lower




Downlink_1930 - 1990 MHz_WCDMA_upper






Downlink_2110 - 2155 MHz_CDMA_lower




Downlink_2110 - 2155 MHz_CDMA_upper






Downlink_2110 - 2155 MHz_GSM_lower




Downlink_2110 - 2155 MHz_GSM_upper






Downlink_2110 - 2155 MHz_WCDMA_lower




Downlink_2110 - 2155 MHz_WCDMA_upper






Downlink_728 - 746 MHz_CDMA_lower




Downlink_728 - 746 MHz_CDMA_upper






Downlink_728 - 746 MHz_GSM_lower




Downlink_728 - 746 MHz_GSM_upper






Downlink_728 - 746 MHz_WCDMA_lower




Downlink_728 - 746 MHz_WCDMA_upper






Downlink_746 - 757 MHz_CDMA_lower




Downlink_746 - 757 MHz_CDMA_upper






Downlink_746 - 757 MHz_GSM_lower




Downlink_746 - 757 MHz_GSM_upper






Downlink_746 - 757 MHz_WCDMA_lower




Downlink_746 - 757 MHz_WCDMA_upper






Downlink_869 - 894 MHz_CDMA_lower




Downlink_869 - 894 MHz_CDMA_upper






Downlink_869 - 894 MHz_GSM_lower




Downlink_869 - 894 MHz_GSM_upper






Downlink_869 - 894 MHz_WCDMA_lower




Downlink_869 - 894 MHz_WCDMA_upper






Uplink_1710 - 1755 MHz_CDMA_lower




Uplink_1710 - 1755 MHz_CDMA_upper






Uplink_1710 - 1755 MHz_GSM_lower




Uplink_1710 - 1755 MHz_GSM_upper






Uplink_1710 - 1755 MHz_WCDMA_lower




Uplink_1710 - 1755 MHz_WCDMA_upper






Uplink_1850 - 1910 MHz_CDMA_lower




Uplink_1850 - 1910 MHz_CDMA_upper






Uplink_1850 - 1910 MHz_GSM_lower




Uplink_1850 - 1910 MHz_GSM_upper






Uplink_1850 - 1910 MHz_WCDMA_lower




Uplink_1850 - 1910 MHz_WCDMA_upper






Uplink_698 - 716 MHz_CDMA_lower




Uplink_698 - 716 MHz_CDMA_upper






Uplink_698 - 716 MHz_GSM_lower




Uplink_698 - 716 MHz_GSM_upper






Uplink_698 - 716 MHz_WCDMA_lower




Uplink_698 - 716 MHz_WCDMA_upper






Uplink_776 - 787 MHz_CDMA_lower




Uplink_776 - 787 MHz_CDMA_upper






Uplink_776 - 787 MHz_GSM_lower




Uplink_776 - 787 MHz_GSM_upper






Uplink_776 - 787 MHz_WCDMA_lower




Uplink_776 - 787 MHz_WCDMA_upper






Uplink_824 - 849 MHz_CDMA_lower




Uplink_824 - 849 MHz_CDMA_upper






Uplink_824 - 849 MHz_GSM_lower




Uplink_824 - 849 MHz_GSM_upper





Uplink_824 - 849 MHz_WCDMA_lower



Uplink_824 - 849 MHz_WCDMA_upper

