




Annex I


Anti-Oscillation



Detection Time_Downlink_1930 - 1995 MHz




Detection Time_Downlink_2110 - 2155 MHz






Detection Time_Downlink_728 - 746 MHz




Detection Time_Downlink_746 - 757 MHz






Detection Time_Downlink_869 - 894 MHz




Detection Time_Uplink_1710 - 1755 MHz






Detection Time_Uplink_1850 - 1915 MHz




Detection Time_Uplink_698 - 716 MHz






Detection Time_Uplink_776 - 787 MHz




Detection Time_Uplink_824 - 849 MHz






Restart Time_Downlink_1930 - 1995 MHz




Restart Time_Downlink_2110 - 2155 MHz






Restart Time_Downlink_728 - 746 MHz




Restart Time_Downlink_746 - 757 MHz






Restart Time_Downlink_869 - 894 MHz




Restart Time_Uplink_1710 - 1755 MHz






Restart Time_Uplink_1850 - 1915 MHz




Restart Time_Uplink_698 - 716 MHz





Restart Time_Uplink_776 - 787 MHz



Restart Time_Uplink_824 - 849 MHz

