



CAUTION

It is normal that the handle might be little heat over working 10 minutes, because the motor is installed in the handle.

标签位置图