



ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022





ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHL170M

File No.: E01NR-022

[Front View of the Hyundai Panel]



ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Rear View of the Hyundai Panel]



ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Front View of the Samsung Panel]



ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHL170M

File No.: E01NR-022



[Rear View of the Samsung Panel]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Top View of the Main Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHL170M

File No.: E01NR-022



[Bottom View of the Main Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHL170M

File No.: E01NR-022



[Top View of the Tuner Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHL170M

File No.: E01NR-022



[Bottom View of the Tuner Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Top View of the OSD Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Bottom View of the OSD Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Top View of the Inverter Board]




ONETECH

Testing & Evaluation Lab.

FCC ID.: PXWHLM170M

File No.: E01NR-022



[Bottom View of the Inverter Board]