



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

February 22, 2005

RE: Netgear Inc.

FCC ID: PY305100001

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) Please provide a proper label for this device. No FCC ID appears on the label sample provided. Kindly confirm that the requested FCC ID is: PY305100001
- 2.) Kindly confirm that for products imported into the USA that only channels 1-11 will be available, and that the end user will be given no ability to change to an operating frequency outside of the USA channel set.
- 3.) This device appears to incorporate a standard USB connector thereby making it possible for the end user to plug this device directly into a notebook PC. Therefore, the 20cm statements in the Manual (two instances on pp.2) are incorrect. Please revise.
- 4.) Item #4 in the Operational Description seems to show that this device is capable of RF powers up to +23dBm. Kindly confirm that the maximum power used with this device is 16mW as indicated on Form 731. Please be advised that this USB device will need SAR testing if the RF power can exceed 24mW.
- 5.) FYI: Please note that in instances where SAR reporting is required, a spectrum analyzer is generally not accurate enough in RF power readings to maintain the required 5% tolerance between SAR report and EMC report. If SAR testing is required, then I will request an alternative RF Pout test.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.