

NETGEAR INC.

2350 East Plumeria Drive, San Jose CA 96134, USA

Tel: 408-890-3657

Fax: 408-907-8097

GUI Declaration letter

Date: 2015-05-13


FCC ID: PY314200260

To Whom It May Concern:

We, Netgear INC. declare that as part of the DFS functionality in the WLAN driver, software is implemented to react to radar detection messages and move to a new channel. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is only can be modify by using a special tool (console cable) which will not be released and won't supply any console pin with the finish product.

Thank you for your attention.

Sincerely yours,



Name: David Kay/ Title: Regulatory Compliance Manager
Netgear INC.

Tel: 408-890-3657

Fax: 408-907-8097

E-mail: David.kay@netgear.com