

350 East Plumeria Drive, San Jose, CA 95134, USA

Date: 2024-02-07

Below is the channel / frequency plan for the device:

[illegible]

NETGEAR, INC.

350 East Plumeria Drive, San Jose, CA 95134, USA

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed.

Sincerely yours,

A handwritten signature in black ink, appearing to read "David Kay", is positioned above a horizontal dashed line.

David Kay, Regulatory Compliance Director
NETGEAR, INC.

Tel: 4088903657

Fax: 4089078097

E-mail: david.kay@netgear.com