



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 7, 2003

RE: NETGEAR, Inc.

FCC ID: PY3WAG311

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The test report was corrected for the conducted photograph issue, however the test configuration photograph still needs correction. Please provide updated test configuration photographs.
- 2) At least 2 antenna connectors are noted from the photographs of the device (on the PCI board and on the mini-PCI board) Please explain if ALL connectors will be soldered and permanently connected in the final product OR if a shield will be placed over this portion of the device so the user does not have access underneath the shield. Note that the users manual and previous products appear to show a shield over a portion of the device. Please confirm which method(s) will be used. If a shield will be used, please provide an additional external photograph that shows this.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.