

Arima Communications Corp.

6F, No. 866, Jhongjheng Rd., Jhonghe Dist., New Taipei City 23586, Taiwan

Tel: 886-2-8227-7755 ; Fax: 886-2-8227-5533

Date: March 25, 2015

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: PY7-PM0860/ FCC ID: PY7-PM0865/ FCC ID: PY7-PM0864/
FCC ID: PY7-PM0863/ FCC ID: PY7-PM0862/ FCC ID: PY7-PM0861

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by the FCC IDs listed above to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,

Jay Chiang Jay Chiang
Apr 8 2015 8:08 PM

Jay Chiang

Jaychiang@arimacomm.com.tw