



Sony Ericsson

Vår handläggare, namn, tfn • *Attending to this matter, name, telephone*
LD/SEM/GUG/NV Håkan Sjöberg +46 46 193559

Statement
Datum • *Date*

2002-08-21

Ert datum • *Your date*

Beteckning • *Reference*

GUG/NV02:230

Er beteckning • *Your reference*

Receiver
Federal Communications Commission

Application: PY71130501

Statement on probe calibration in report GTX/FG 02:005

The probe used in Sony Ericsson SAR report GTX/FG 02:005 was not calibrated for 1900 due to lack of calibration resources. This was caused by the new European rules being implemented making all SAR systems recalibrating. Based on our experience the maximum differences between 1800 and 1900 calibration is maximum 3%. Due to this we used the 1800 calibration for the 1900 measurements.

Since the issue of the report calibration for 1900 has been performed.

Regards,

Mats Hansson

Senior Staff Engineer - Type Approvals/Verification
Sony Ericsson Mobile Communications AB
Nya Vattentornet
221 88 Lund
Sweden

Telephone: +46 46 193357
E-mail: mats.hansson@sonyericsson.com

Sony Ericsson Mobile Communications AB

Postadress • *Mail*
SE-221 88 Lund
Sweden

Besöksadress • *Office address*
Nya Vattentornet
Lund

Styrelsens säte: Lund
Registered office: Lund
Telefon • *Telephone*
Nat 046-19 40 00
Int +46 46 19 40 00

Momsnr • *V.A.T.No:* SE556615665801
Organisationsnr • *Reg No:* 556615-6658
Telefax • *Telefax*
Nat 046-19 41 00
Int +46 46 19 41 00