

Company: Radwin

Product Name: RADWIN 2000 JET, RADWIN 5000 JET


Report No.: RDWN47 – Internal Photos

PHOTOS - INTERNAL




1. Internal Photographs


1.1.1. Product - Internal




Antenna Assembly




Antenna Assembly in Housing



Antenna IO Board Back View




Antenna IO board Front View



Antenna IO Board in Housing



Mainboard and RF Module in Housing




Mainboard Back View


This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




MiCOM Labs, 575 Boulder Court, Pleasanton, California 94566 USA, Phone: +1 (925) 462 0304, Fax: +1 (925) 462 0306, www.micomlabs.com




RF Module Back View Headsink off



RF Module Back View Heatsink on



RF Module Front View Shield off



RF Module Front View Shield on



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com