



HERMON LABORATORIES

June 10, 2004

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. D. Ward, Examining Engineer

RE: your e-mail dated June 6, 2004; Radwin Ltd.
FCC ID: Q3KAMWL1000, ATCB001398

Dear Mr. Ward,
Please find below the answers to your questions.

- 1) Radwin Ltd. confirms that the two products WinLink 1000 and AirMux-200 are exactly the same, just they have 2 commercial names for marketing purposes.
- 2) Revised file "Label_location_15885_rev1" was uploaded via Label Location folder on June 10, 2004.
- 3) Revised file "User_Manual_15885_rev1" with corrected page 14 (about class B requirements) was uploaded via Users Manual folder on June 10, 2004.

Many thanks for your help.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories