



September 13, 2004

Linda Elliot
FCC Application Processing Branch
Federal Communications Commission
445 12th Street, SW
Washington, DC 20554

RE: FCC ID Q4DPSC5210W

Dear Ms. Elliot:

Advanced Bionics is submitting the following information in regards to your E-mail dated September 13, 2004.

1. The FCC ID is not shown on the identification label, pursuant to Section 2.925(a)(1) of the FCC Rules. Submit a revised identification label, as appropriate.

The Remote Control does not have an identification label per se. Instead, the requisite information is laser-marked into the case. The documentation submitted contains a file named "SCS2 RC label", which contains a draft version of the artwork that will be used to mark Remote Control cases once approval has been granted. The picture titled "SCS 2 RC Bottom View" shows how our current artwork version appears on the case.

2. Our records show that the filing fee has not been paid. Please clarify if this is the case; and if so you must pay the filing fee immediately to avoid cancelation of your request.

The fee was delivered to Mellon Bank on September 13, 2004 under FedEx tracking number 603944918007 and signed for by L. Childs.

Sincerely,

for

Kaoru Lee Adair, Vice President
Regulatory Affairs and Clinical Research