



Photograph of inside MT16U case.




ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Speedcam, Inc.
MODEL: MT16U
Test #: 060515U
Test to: FCC Parts 2 and 90

IC: 6725A-HHTU1
FCCID#: Q4X-HHTU1
Page 1 of 2

MT16U Internal Photo.doc 9/19/2006

Please refer to schematics exhibit for PCB layout and component locations located under shields.



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Speedcam, Inc.
MODEL: MT16U
Test #: 060515U
Test to: FCC Parts 2 and 90

IC: 6725A-HHTU1
FCCID#: Q4X-HHTU1
Page 2 of 2

MT16U Internal Photo.doc 9/19/2006