



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 1
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 2
FCC ID: Q6C-NSLK3200






Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 4
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 5
FCC ID: Q6C-NSLK3200





Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 7
FCC ID: Q6C-NSLK3200





Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 9
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 10
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 11
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 12
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 13
FCC ID: Q6C-NSLK3200






Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 16
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 17
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 18
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 19
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 20
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 21
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 22
FCC ID: Q6C-NSLK3200









Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 25
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 26
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 27
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 28
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 29
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 30
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 31
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 32
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200


Photo # 33
FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 34
FCC ID: Q6C-NSLK3200








Annex 3 – Internal Photos of EUT

Norsat Newslink, Model 3200

Photo # 37

FCC ID: Q6C-NSLK3200




Annex 3 – Internal Photos of EUT

Norsat Newslink, Model 3200

Photo # 38

FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT
Norsat Newslink, Model 3200

Photo # 39
FCC ID: Q6C-NSLK3200



Annex 3 – Internal Photos of EUT

Norsat Newslink, Model 3200

Photo # 40

FCC ID: Q6C-NSLK3200

