

Response to E04-000087-1

1. The label location has been uploaded in the proper format.
2. Testing was performed below 30 MHz, but no emissions were found.