



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 6, 2004

RE: Cisco-Linksys, LLC.

FCC ID: Q87-HGA7S-3

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative Issues:

- 1) The block diagram should show the frequencies of all oscillators in the TX portion of the device (CFR 2.1033(a)(5)). It appears only the system level block diagram was provided. Please provide the block diagram for the TX portion. However, if the TX portion of this device is an OEM part, as an alternative, you may provide a parts list that lists that shows that this part is provided by another manufacturer. Please provide either a block diagram for the TX or a parts list as specified. If necessary, please update the confidentiality request letter to cover the parts list if provided.
- 2) A schematic for the TX portion of the device is required as specified 2.1033(b)(5) for the RF section. However, if the TX portion of this device is an OEM part, as an alternative, you may provide a parts list that lists that shows that this part is provided by another manufacturer. Please provide either a schematic for the TX or a parts list as specified. If necessary, please update the confidentiality request letter to cover the parts list if provided.
- 3) All antennas given in the photographs appear to be +7 dBi gain antennas for both mode A & B, while the RF exposure also mentions +5 dBi gain antennas. Please explain.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.