



LINKSYS®
A Division of Cisco Systems, Inc.
17401 Armstrong Ave.,
Irvine, CA 92614

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer
Subject: Request to change in identification per section 2.933 of FCC rules
Reference: FCC ID: Q87-WPC55AGV11

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Cisco-Linksys, LLC. will establish a new FCC ID under Cisco-Linksys, LLC. grantee code for purpose of marketing. The original grant to Atheros Communications, Inc. FCC ID: PPD-AR5BCB-00032 will remain in effect.

An authorization letter by Atheros Communications, Inc. is attached.
Per 2.933(b)

1. The original identification is PPD-AR5BCB-00032.
2. The original grant date is August 22, 2003.
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,


Cisco-Linksys, LLC
Name: Jennifer Yu
Title: Associate Engineer
Date: September 16, 2003