



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 19, 2004

RE: Cisco-Linksys, LLC.

FCC ID: Q87-WU54GPV4

After a review of the submitted information, I have a few comments on the above referenced Application.

SAR REPORT

- 1) The probe calibration information on the plots (4.6, 4.6, 4.6) does not appear to agree with calibration information or the information on page 6. It appears the probe information given is for the incorrect S/N.
- 2) The dipole validation information appears outdated. Please provide the correct information that matches the required value on page 23 (14.3).
- 3) The Standard Value for 2462 MHz for Conductivity on page 20 appears incorrect. Please review.
- 4) The measurement Value for 2462 Permittivity on page 20 appears out of spec or incorrect. Please review.
- 5) The liquid parameter values specified on the plots do not appear to match page 20. Please explain.
- a) FYI....Note that check for consistency in liquid parameters in calibration, system verification, and device testing could not be verified due to questions above.

USERS MANUAL

- 6) Information in the users manual should identify SAR spacing and/or approved test configurations (page 44).
- 7) FYI...Declaration of Conformity information in the manual is lacking information. All the following information should be placed on a single page in the users manual for the end user.

COMPLIANCE INFORMATION FOR DoC AUTHORIZATIONS (47CFR 2.1077)

If a product is tested and authorized under a Declaration of Conformity, a compliance information statement shall be supplied with the product at the time of marketing or importation, containing the following information on a single page (as a separate sheet or in the users manual):

- (1) Identification of the product, i.e. name and model number. NOTE THIS IS ALREADY ON PAGE 44.
- (2) A statement similar to that contained in Section 15.19(a)(3) that the product complies with Part 15 of the regulations. NOTE THIS IS ALREADY ON PAGE 44.
- (3) The identification, by name, address and telephone number, of the responsible party. The responsible party is defined as either the manufacturer, or if the equipment is imported, the importer. The responsible party for a Declaration of Conformity must be located within the United States. THIS INFORMATION APPEARS TO BE MISSING FROM PAGE 44.



Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.