



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 9, 2003

RE: Cisco-Linksys, LLC
FCC ID: 17401 Armstrong Avenue

I have a few comments on this Application.

- 1.) Please supply External Photographs for this device.
- 2.) Please supply Internal Photographs for this device.
- 3.) The RF Pout listed in the Test Report does not match the Form 731.
- 4.) The RF Pout listed in the RF Exposure information does not match Form 731.
- 5.) The Users Manual is broken up into five pieces that total over 15.8MB. I dare not upload this Manual in present form to the FCC website. Please supply a much, much smaller manual.
- 6.) Although a Label is supplied, there is no information as to where it will be located on this device. Please supply location information.

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.