



INNOVATIVE COMMUNICATION SOLUTIONS

Labels Exemplary

G-Wave, Inc.
MODEL: BDA-UHF-36/36-80-N
FCC ID Q8KUHF3680N IC: 4901A-UHF3680N
SER.No: 15031001 (411.5 MHz)

**This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received,
that may cause undesired operation.**

WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

**This device is a Part 90
Signal Booster and a
90.219 Class B device.**

*The labels having adhesive back.

**This device is a Part 90
Signal Booster and a
90.219 Class B device.**


WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.

G-Wave, Inc.

MODEL: BDA-UHF-36/36-80-N

FCC ID Q8KUHF3680N IC: 4901A-UHF3680N

SER.No: 15031001 (411.5 MHz)



This device is a Part 90
Signal Booster and a
90.219 Class B device.



Copyright © 1999, by MCI Telecommunications Corporation. All rights reserved. The information contained herein is confidential and proprietary to MCI Telecommunications Corporation. It is not to be distributed, copied, or otherwise used in any manner without the prior written consent of MCI Telecommunications Corporation. MCI Telecommunications Corporation is not responsible for any errors or omissions in this document. MCI Telecommunications Corporation is not responsible for any damages, including consequential damages, arising from the use of this document. MCI Telecommunications Corporation is not responsible for any damages, including consequential damages, arising from the use of this document.

WARNING:
THE WARRANTY IS VOID IF THE ISOLATION BETWEEN THE BASE ANTENNA AND THE MOBILE ANTENNA IS NOT CONFIGURED AT LEAST 12dB HIGHER THAN THE ROA GAIN. ISOLATION EQUAL OR LESS THAN THE ROA GAIN WILL RESULT IN DAMAGE TO THE ROA.

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and
(2) This device must accept any interference received,
that may cause undesired operation.