40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		

40-90 Vac Made in Canada **IP68 14P16**	**Lindsay Broadband Inc.** FCC ID: Q9DAPEX0104 IC ID: 4675A-APEX0104	**Model: APEX0104**	**SKU: 5-1893 SMHAP-AP270**	Radio: CM:
		This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		