Company: Aruba Networks

Model Number: WAP3212

Report No.: ARUB189 - WAP 3212 Internal Photographs

Internal Photographs

INTERNAL EUT PHOTOGRAPHS

Aruba Networks WAP3212

Report No.: ARUB189 - WAP 3212 Internal Photographs

Applicant:	Aruba Networks 1344 Crossman Ave. Sunnyvale 94089-1113, United States
Product Function:	Cabin Wireless Access Point Part Number: WAP3212-001-001 RD-FA2066-01
Issue Date:	4th February 2015

Issued Under the Authority of:

MiCOM Labs, Inc.
575 Boulder Court
Pleasanton, California 94566
USA
Phone: +1 (925) 462-0304
Fax: +1 (925) 462-0306
www.micomlabs.com

ACCREDITED
TESTING CERT #2381.01

MiCOM Labs is an ISO 17025 Accredited Testing Laboratory

1. Internal Photographs

1.1. Product - Internal



Topside - Controller Board P/N: 13029025-320



Bottomside - Controller Board P/N: 13029025-320

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Topside - Power Board P/N: 13029025-420

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Bottomside - Power Board P/N: 13029025-420

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Internal assembly - Connector-Board / LED-Board / Antenna-Wiring

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Internal assembly - Connector-Board / Flex-Cable

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Internal assembly - LED-Board / Maintenance-Jack

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Internal assembly - Connector-Board / Heatsink with installed Radio-Board (P/N:13029025-701)

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Bottomside - Radio-Board P/N: 13029025-701

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Topside - Radio-Board P/N: 13029025-701

This report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.

575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com