



Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

Component side; first half




## Component side; second half




Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

Solder side; first half



Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

Solder side; second half



Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

## Test Setup: Line Conducted



Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

## Test Setup: Line Conducted





Stryker Instruments  
TPS Plus new control board  
FCC ID: Q9R-5100  
06-06-2005

## Test Setup: Radiated (back of EUT)

