

Marianne Bosley

From: Marianne Bosley
Sent: Friday, September 27, 2002 8:43 AM
To: Marianne Bosley
Subject: FW: Mozart and Wolfgang - DL into network - already printed out

-----Original Message-----

From: Lohoff, Torsten
To: 'MBosley@metlabs.com'
Sent: 9/27/2002 6:59 AM
Subject: AW: Mozart and Wolfgang

Hello,

correct, due to the fact that both products (Wolfgang and Mozart) are electrically identical, also the parts lists are identical. It is not possible for the customer to tuneup the device. Everything is calibrated/tuned at manufacture.

Best Regards

Torsten

-----Ursprüngliche Nachricht-----

Von: MBosley@metlabs.com [mailto:MBosley@metlabs.com]
Gesendet: Donnerstag, 26. September 2002 17:07
An: Lohoff, Torsten
Betreff: Mozart and Wolfgang

Hi again,

I apologize for repeat on my part, but could you confirm that the parts list for Wolfgang is the same as the partslist for Mozart.

Also, could you say what the tuneup procedure for these are. If it is calibrated/tuned at manufacture and there aren't any further requirements for customer tuneup, please just state that. It is a requirement for something to be submitted for that exhibit.

Your applications have passed Part 24 technical review, and they are now in the hands of Chris Harvey for SAR review. Thank you for the above that I have requested.

Have a good day.

Marianne

Marianne T. Bosley
EMC Administrator
410-354-3300 X 412
mbosley@metlabs.com