

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0003

Page (48) of (51)


KCTL

Appendix C. Test Photo

Front (5 mm)



Rear (5 mm)




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr


Report No.:
KR17-SPF0003
Page (49) of (51)

KCTL

Left (5 mm)



Right (5 mm)





KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0003

Page (50) of (51)

KCTL**Top (5 mm)****Bottom (5 mm)**

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0003


Page (51) of (51)

KCTL

System Check 2 450 MHz



Liquid Depth MSL 2450



- END OF REPORT -

This test report shall not be reproduced, except in full, without the written approval.

KCTL-TIA002-004/1