



BROADCOM CORPORATION
190 Mathilda Place
Sunnyvale, CA 94806

Phone: 408-543-3300
Fax: 408-543-3399

Date: January 7, 2015

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: QDS-BRCM1085
(Original Grant Date: November 20, 2014)
Applicant: Broadcom Corporation

Dear Examiner,

This is to request a Class II permissive change for FCC ID: QDS-BRCM1085. There is no hardware or electrical modifications made to the applying modular transmitter.

The major change filed under this application is:

1) Change: Adding CH13 to original approval.

If you have any questions regarding this application, please feel free to contact me.
Sincerely yours,

A handwritten signature in black ink, appearing to read "Daniel Lawless", is written over a horizontal line.

Daniel Lawless
Director of Engineering,
Systems Operations
Broadcom Corporation
190 Mathilda Place,
Sunnyvale, CA 94086

Date: January 7, 2015



BROADCOM CORPORATION
190 Mathilda Place
Sunnyvale, CA 94806

Phone: 408-543-3300
Fax: 408-543-3399

Certification and Engineering Bureau
Industry Canada
Spectrum Engineering Branch
3701 Carling Avenue, Building 94
Ottawa, Ontario K2H 8S2

Attn: OET Dept.

Ref: Re-Assessment (Modification) for IC Certification No: 4324A-BRCM1085
(Original Grant Date: November 24, 2014)
Applicant: Broadcom Corporation

Dear Examiner,

This is to request a Re-Assessment (Modification) for IC Certification No:
4324A-BRCM1085, originally granted on November 24, 2014. There is no hardware
or electrical modifications made to the applying modular transmitter.

The major change filed under this application is:

- 1) Change: Change: Adding CH13 to original approval.

If you have any questions regarding this application, please feel free to contact me.

Sincerely yours,

A handwritten signature in black ink, appearing to read 'Daniel Lawless', is written over a horizontal line. The signature is fluid and cursive, with a long, sweeping underline that extends to the right.

Daniel Lawless
Director of Engineering,
Systems Operations
Broadcom Corporation
190 Mathilda Place,
Sunnyvale, CA 94086