



Model 5100 worst case setup for measurements $<1\text{GHz}$



Model 5100 setup for measurements $<28\text{MHz}$



Model 5100 setup for measurements $>1\text{GHz}$