



Stenkullen 2003-02-19

TIMCO ENGINEERING, INC.
Sharon A. Hoffman
849 N.W. STATE ROAD 45
P.O. BOX 370
NEWBERRY, FL 32669

Subject: Re: FCC ID: QF9LOCAL

Icom 4008 Series block diagram

There is only a digital copy of the material available
for the European version of the radio.
The service manual will include the correct block diagram for the
American market.

Fredrik Ström

Technical Manager
Hellberg Safety AB

Hellberg Safety AB
Box 3002
443 02 Stenkullen

Besöksadress:
Org.nr:

Stakebergsvägen 2
556214-4898

Tel.nr. 46 302 24450
Fax.nr. 46 302 24460