



Stenkullen 2003-02-19

TIMCO ENGINEERING, INC.
Sharon A. Hoffman
849 N.W. STATE ROAD 45
P.O. BOX 370
NEWBERRY, FL 32669

Subject: Re: FCC ID: QF9LOCAL

This FRS radio model is electronically the same as the Icom 4008 Series and therefore the alignment procedure will work for both models. A note will be included in the service manual to the American technician that the device must be tuned to the proper frequencies for the USA Market.

Fredrik Ström

Technical Manager
Hellberg Safety AB

Hellberg Safety AB
Box 3002
443 02 Stenkullen

Besöksadress:
Org.nr:

Stakebergsvägen 2
556214-4898

Tel.nr. 46 302 24450
Fax.nr. 46 302 24460