



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 23, 2003

RE: Nokia UK Ltd.

FCC ID: QFXNHM-10X

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) We did not realize that the Bluetooth was a installed module. Part 15 (bluetooth approval) requires the top and bottom of each board photographed. Please provide an additional bottom photograph of the module.
- 2) For previous question 3), please confirm if the device is a dual-band or tri-band phone. Note that the theory of operation mentions dual-band Cell phone, but section 2 of the EMC report states tri-band. Please explain.

Bluetooth Report

- 3) Previous question 7) & 8) should have stated that the VBW (not RBW) must be $> 1/TX$ on time. Please recommend on this question.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.