

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0005-C
Page (96) of (99)


KCTL

Appendix C. Test Photo

Front(Ant.1)



Front(Ant.2)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr


Report No.:
KR17-SPF0005-C
Page (97) of (99)

KCTL**System Check 2 450 MHz****System Check 5 000 MHz**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr



Report No.:
KR17-SPF0005-C
Page (98) of (99)

KCTL**Liquid Depth HSL 2 450****Liquid Depth MSL 2 450**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
Tel : 82-31-285-0894 Fax : 82-505-299-8311
www.kctl.co.kr

Report No.:
KR17-SPF0005-C
Page (99) of (99)

KCTL**Liquid Depth HSL 5 000****Liquid Depth MSL 5 000**

- END OF REPORT -

This test report shall not be reproduced, except in full, without the written approval.

KCTL-TIA002-004/1