



Appendix C. Test Photo

Front(Ant.1)



Front(Ant.2)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-70-5008-1021 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR16-SPF0003-B
Page (86) of (89)

KCTL**Front(Ant.3)**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-70-5008-1021 FAX: 82-505-299-8311
www.kctl.co.kr



Report No.:
KR16-SPF0003-B
Page (87) of (89)

KCTL**System Check 2 450 MHz****System Check 5 000 MHz**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-70-5008-1021 FAX: 82-505-299-8311
www.kctl.co.kr



Report No.:
KR16-SPF0003-B
Page (88) of (89)

KCTL**Liquid Depth HSL 2450****Liquid Depth MSL 2450**

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-70-5008-1021 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR16-SPF0003-B
Page (89) of (89)

KCTL**Liquid Depth HSL 5000****Liquid Depth MSL 5000**

- END OF REPORT -