

Appendix D

Spurious Emission at Antenna Terminal Measurements

According to CFR 47 (FCC) part 2.1051


Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 2 von 9

Page 2 of 9

* Agilent 18:11:04 Jul 18, 2002




Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 3 von 9

Page 3 of 9

Agilent 18:12:49 Jul 18, 2002




Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 4 von 9

Page 4 of 9

* Agilent 18:16:02 Jul 18, 2002



Marker	Trace	Type	X Axis	Amplitude
1	(1)	Freq	2.620 GHz	-61.63 dBm
2	(1)	Freq	1.180 GHz	-73.67 dBm

Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 6 von 9

Page 6 of 9

✱ Agilent 18:20:16 Jul 18, 2002

Ref 0 dBm

Atten 10 dB

Peak

Log

10

dB/

DI

-13.0

dBm

LgAv

M1 S2

Start 1.000 GHz

Stop 10.000 GHz

*Res BW 1 MHz

VBW 1 MHz

Sweep 15 ms

Marker	Trace	Type	X Axis	Amplitude
1	(1)	Freq	2.620 GHz	-55.56 dBm
2	(1)	Freq	7.045 GHz	-69.57 dBm
3	(1)	Freq	8.770 GHz	-70.47 dBm


Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 7 von 9

Page 7 of 9

Agilent 18:00:44 Jul 18, 2002




Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 8 von 9

Page 8 of 9

* Agilent 18:01:55 Jul 18, 2002




Prüfbericht - Nr.: 17000535 001

Test Report No.

Seite 9 von 9

Page 9 of 9

Agilent 17:51:36 Jul 18, 2002



Marker	Trace	Type	X Axis	Amplitude
1R	(1)	Freq	872.12 MHz	34.21 dBm
1 Δ	(1)	Freq	-1.28 MHz	-55.94 dB
2R	(1)	Freq	874.86 MHz	37.88 dBm
2 Δ	(1)	Freq	1.74 MHz	-56.34 dB