



Huawei Technologies Co., Ltd.

2014-08-15

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

Certification and Engineering Bureau
Industry Canada
Spectrum Engineering Branch
3701 Carling Avenue, Building 94
Ottawa, Ontario K2H 8S2

PCII Request / Re-assessment

<MC323> , FCC ID: <QISM323> granted on <2011-11-22>

and IC: < 6369A-MC323 > granted on < 2011-11-22 >

TO WHOM IT MAY CONCERN

Pursuant to CFR § 2.1043 and RSP-100, < Huawei Technologies Co., Ltd.> hereby requests a
Permissive Change Class II / Re-assessment.

Reason: The old RF duplexer (PANASONIC EFSD836MK3T1) was already EOL, so MC323 has to apply
new RF duplexer (MURATA SAYRJ836MCA0F0AR05), So only duplexer is deference.

Description of the change:

Slight HW change due to exchange of absolute component. For more detail please check:

- Operation Description--- Detail description of changes
- Bom List
- External Photos

The following documents from the original application remain unchanged, applicable and
representative after Class II Permissive change:

- Block Diagram
- Tune-up procedure
- Label
- Label location
- User Manual

Sincerely,

Zhang Xing hai
EMC Laboratory Manager
For and Behalf of:
Huawei Technologies Co., Ltd.

Huawei Industrial Base, Bantian, Longgang, Shenzhen, P.R China