

Prüfbericht - Nr.: 17002468 001

Test Report No.

Seite 2 von 17


Page 2 of 17

Appendix D


Spurious Emission at Antenna Terminal Measurements

According to CFR 47 (FCC) part 2.1051


Measurement Result at Block Edge
Channel 25(1931.25MHz)




Channel 275(1943.75MHz)




Channel 325(1946.25MHz)




Channel 875(1973.75MHz)




Channel 925(1976.25MHz)






Channel 1175(1988.75MHz)





Measurement Result Outband Band Edge
Channel 25
















Channel 1175










ACPR Test according to EIA/TIA 97D-2001

Channel 1000



Prüfbericht - Nr.: 17002468 001

Test Report No.

Seite 18 von 17

Page 18 of 17

