

Appendix E


Field Strength of Spurious Radiation Measurements

According to CFR 47 (FCC) part 2.1053

The Result of Spurious Radiation Test

1. BTS3601 Test Result

One carriers have been work normally. BTS work at frequency
No.1000(1980.00MHz)





Prüfbericht - Nr.: 17002468 001

Test Report No.

Seite 3 von 11

Page 3 of 11







The point which exceeds the limit line is the carrier frequency.

Prüfbericht - Nr.: 17002468 001
Test Report No.

Seite 5 von 11
Page 5 of 11



The Result of Substitute Test



Prüfbericht - Nr.: 17002468 001


Test Report No.

Seite 7 von 11

Page 7 of 11

2. ODU3601 Test Result

One carriers have been work normally. BTS work at frequency
No.1000(1980.00MHz)





Prüfbericht - Nr.: 17002468 001

Test Report No.

Seite 8 von 11

Page 8 of 11







The point which exceeds the limit line is the carrier frequency.

Prüfbericht - Nr.: 17002468 001
Test Report No.

Seite 10 von 11
Page 10 of 11



The Result of Substitute Test



END