

RF exposure compliance issues:

The unit uses a very low eirp level of not more than 10 mW. So it is excluded from routine RF exposure evaluation.