


External photos



Kill switch, must be constantly depressed. When switch is released, pulse generator will cease firing pulses within 10 seconds.