




APPENDIX N: INTERNAL PHOTOGRAPHS



PHOTOGRAPH 12: THE LID



PHOTOGRAPH 13: INSIDE THE BOX – LEFT SIDE




PHOTOGRAPH 14: INSIDE THE BOX – RIGHT SIDE

Client: Vivato, Inc.
Report number: 2002148
FCC Standard: Part 15.247
FCC ID: QLN-DP2310P0001
Model Name: Wireless Packet Switch



Page 133 of 177




PHOTOGRAPH 16: AC LINE FILTER IMPLEMENTATION #2




PHOTOGRAPH 17: AC LINE FILTER IMPLEMENTATION #3




PHOTOGRAPH 18: AC LINE FILTER IMPLEMENTATION #4




PHOTOGRAPH 19: AGERE MINIPCI RADIO TOP WITH SHIELDS



PHOTOGRAPH 20: AGERE MINIPCI RADIO BOTTOM WITH SHIELD




PHOTOGRAPH 21: AGERE MINIPCI RADIO TOP WITHOUT SHIELDS




PHOTOGRAPH 22: AGERE MINIPCI RADIO BOTTOM WITHOUT SHIELD




PHOTOGRAPH 23: PCI ADAPTER WITH RADIO




PHOTOGRAPH 24: PCI ADAPTER BOTTOM



PHOTOGRAPH 25: BUTLER MATRIX FRONT



PHOTOGRAPH 26: BUTLER MATRIX BACK



PHOTOGRAPH 27: BUTLER MATRIX ASSEMBLED