11-15-02

FROM: JOHN KENNEDY
Homewatch L.L.C. / ResponseLINK L.L.C.
13649 Granville Clermont Fl. 34711
407-877-4400
HomeWatchRepair@aol.com
Regarding part 15 wireless smoke detector application.

F.C.C. c/o Richard Fabina

Mr. Fabina- Earlier this year Homewatch L.L.C. purchased specific finished goods inventory and future manufacturing rights to some devices subject to part 15 compliance from Advantor Corporation of Orlando Florida. One of the items is a wireless smoke detector that carried an F.C.C. grant number of

NG6POMSMOKE

We wish to retitle the previously FCC granted equipment under Advantor to our HomeWatch L.L.C. name.

Our HomeWatch L.L.C. F.C.C. registration number is 0007797830

I am now stating that HomeWatch L.L.C. agrees to manufacture this device with the exact design , bill of materials and specifications purchased from Advantor which were previously listed with you.

I am advising you that all Advantor test fixtures were purchased also. This should ensure continued manufactured product compliance within the F.C.C. guidelines we are subject to with this device.

I have completed the F.C.C. 731 application and have uploaded photos , this cover letter and the previous F.C.C. grant issued to Advantor for the smoke detector.

Thank You, John Kennedy
Technical Specialist HomeWatch L.L.C.
Email: HomeWatchrepair@aol.com