



HERMON LABORATORIES

January 8, 2004

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated January 6, 2004; WaveIP Ltd.
FCC ID: QQ2-GA24-RSU, ATCB000992

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) We are awaiting for your message.
- 2) Unintentional radiated emissions were retested. The revised test report WAVRAD_FCC.15569_rev2 with changed section 4.6 and plots A87, A88, new file Setup_photos_15569_amendment were uploaded on January 8, 2004.
- 3) The duty cycle was additionally measured, please refer to file "Duty_cycle_15569", uploaded on January 8, 2004 via Additional information folder.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories