







EQUIPMENT: BDA-CELLAB-2/2W-60-BX





EQUIPMENT: BDA-CELLAB-2/2W-60-BX





EQUIPMENT: BDA-CELLAB-2/2W-60-BX





EQUIPMENT: BDA-CELLAB-2/2W-60-BX



EQUIPMENT: BDA-CELLAB-2/2W-60-BX



EQUIPMENT: BDA-CELLAB-2/2W-60-BX



Section 5. Spurious Emissions at Antenna Terminals

Para. No.: 2.1051

Test Performed By: Kevin Carr	Date of Test: 13 Dec. 2002
--------------------------------------	-----------------------------------



Minimum Standard: 22.917(e): -13dBm
(f): -80dBm

Test Results: Complied.



Measurement Data: See attached graphs. Only worst case has been reported

EQUIPMENT: BDA-CELLAB-2/2W-60-BX



Uplink





EQUIPMENT: BDA-CELLAB-2/2W-60-BX





EQUIPMENT: BDA-CELLAB-2/2W-60-BX





EQUIPMENT: BDA-CELLAB-2/2W-60-BX



EQUIPMENT: BDA-CELLAB-2/2W-60-BX



EQUIPMENT: BDA-CELLAB-2/2W-60-BX



EQUIPMENT: BDA-CELLAB-2/2W-60-BX

