





EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60





EQUIPMENT: BDA-SMR-2/2W60-N89
FCC ID:QQRBN892W60





EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60





EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60



EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60



EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60

Section 5. Spurious Emissions at Antenna Terminals

Para. No.: 2.991

Test Performed By: Kevin Carr	Date of Test: 20 Dec. 2002
--------------------------------------	-----------------------------------



Minimum Standard: -13 dBm

Test Results: Complied.

Measurement Data: See attached graph(s).



EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60





EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60



EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60



EQUIPMENT: BDA-SMR-2/2W60-N89

FCC ID:QQRBN892W60

