







Date: 10.SEP.2003 15:07:50




Date: 10.SEP.2003 15:08:17




Date: 10.SEP.2003 15:08:55



Date: 10.SEP.2003 15:09:44




Date: 10.SEP.2003 15:10:06




Date: 10.SEP.2003 15:10:45


Channel 11:




Date: 10.SEP.2003 15:12:13




Date: 10.SEP.2003 15:13:07




Date: 10.SEP.2003 15:13:42




Date: 10.SEP.2003 15:15:51




Date: 10.SEP.2003 15:16:24




Date: 10.SEP.2003 15:17:11




Date: 10.SEP.2003 15:19:33



Date: 10.SEP.2003 15:20:42



Date: 10.SEP.2003 15:22:14




Date: 10.SEP.2003 15:22:37

FCC TEST REPORT

Report No. : F382007

Mode 4 ~ Mode 6

(Channel 1):



Date: 10.SEP.2003 15:28:38

SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC ID. : QS3WGDII1

Page No. : 17 of 46


Issued Date : Sep. 22, 2003




Date: 10.SEP.2003 15:29:37




Date: 10.SEP.2003 15:30:15




Date: 10.SEP.2003 15:30:43




Date: 10.SEP.2003 15:31:06




Date: 10.SEP.2003 15:31:39




Date: 10.SEP.2003 15:32:11



Date: 10.SEP.2003 15:33:11




Date: 10.SEP.2003 15:33:43




Date: 10.SEP.2003 15:34:16


Channel 6:




Date: 10.SEP.2003 15:36:22




Date: 10.SEP.2003 15:40:19




Date: 10.SEP.2003 15:40:41




Date: 10.SEP.2003 15:42:30




Date: 10.SEP.2003 15:42:51



Date: 10.SEP.2003 15:43:58




Date: 10.SEP.2003 15:44:19




Date: 10.SEP.2003 15:44:53



Ref 0 dBm *Att 10 dB *RBW 100 kHz
*VBW 100 kHz *SWT 500 ms



Date: 10.SEP.2003 15:50:05




Date: 10.SEP.2003 15:53:09

FCC TEST REPORT

Report No. : F382007

Channel 11:



Date: 10.SEP.2003 15:55:18

SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC ID. : QS3WGDII1

Page No. : 37 of 46

Issued Date : Sep. 22, 2003

FCC TEST REPORT

Report No. : F382007



Date: 10.SEP.2003 15:55:53

SPORTON International Inc.


TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


FCC ID. : QS3WGDII1

Page No. : 38 of 46


Issued Date : Sep. 22, 2003




Date: 10.SEP.2003 15:56:20




Date: 10.SEP.2003 15:56:59




Date: 10.SEP.2003 15:57:19




Date: 10.SEP.2003 15:58:26




Date: 10.SEP.2003 16:00:01



Date: 10.SEP.2003 16:00:22



Date: 10.SEP.2003 16:00:58



Date: 10.SEP.2003 16:02:30