

Appendix 2 Photodocumentation

Description: Detecting Loops

Medizintechnik/Nachrichtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 3 of 40

Date: 25.02.2004

checked by: *[Signature]*



Appendix 2 Photodocumentation

Description: PCB sd547_4 Component Side #1

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 4 of 40

Date: 25.02.2004

checked by: *MM*



Appendix 2 Photodocumentation

Description: PCB sd547_4 Component Side #2

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 5 of 40

Date: 25.02.2009

checked by: 



Appendix 2 Photodocumentation

Description: PCB sd547_4 Solder Side

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 6 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Cabling #1


Medizintechnik/Nach-
richtentechnik/EMV

Department: EMC

Test report reference:
M/EMV-04/121

Page: 7 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Cabling #2

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 8 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Cabling #3 (Ferrite)

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 9 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Photo Sensor #1 (Front)

Medizintechnik/Nach-
richtentechnik/EMV

Department: EMC

Test report reference:
M/EMV-04/121

Page: 10 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Photo Sensor #2 (Back)

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 11 of 40

Date: 25.02.2004

checked by: *jm*



Appendix 2 Photodocumentation

Description: Signal Lamps

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 12 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: PCB sd420_5 Component Side

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 13 of 40

Date: 25.02.2004

checked by: *[Signature]*



Appendix 2 Photodocumentation

Description: PCB sd420_5 Solder Side

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 14 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Rotary Spray Mechanical View

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 15 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: RF-Modul General View #1 (Top)

Medizintechnik/Nachrichtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 16 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: RF-Modul General View #2 (Side)

Medizintechnik/Nach-
richtentechnik/EMV

Department: EMC

Test report reference:
M/EMV-04/121

Page: 17 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: RF-Modul PCB sd580_5
Component Side

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 18 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: RF-Modul PCB sd580_5 Solder Side

Medizintechnik/Nach-
richtentechnik/EMV


Department: EMC

Test report reference:
M/EMV-04/121

Page: 19 of 40

Date: 25.02.2004

checked by: 



Appendix 2 Photodocumentation

Description: Fit All-Modul General View #1
(Front)

Medizintechnik/Nach-
richtentechnik/EMV

Department: EMC

Test report reference:
M/EMV-04/121

Page: 20 of 40

Date: 25.02.2004

checked by: 

