

TIMCOENGINEERING INC.

849 NW State Road 45

Newberry, Florida 32669

<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: tei@timcoengr.com

February 21, 2003

FCC

SUBJECT: YOUNG ELECTRONICS CORPORATION - FCC ID: QT2EMS1YOUNG

REFERENCE: DUTY CYCLE CORRECTION FACTOR

To Whom It May Concern:

The correct duty cycle correction factor for this device was calculated at 17% (-15.6dB). This correction factor was not applied to the final Radiated Emissions Data Table. However, the radiated emission data for this device is still within limits. The device is a key chain, hand-held car door opener. Instructions are being sent to this laboratory describing the correct method for calculating duty cycle.

Very truly yours,
Frank DeNuzzo