





NOTICE
WAFFER BREAKAGE HAZARD
Vacuum Bagging May Cause
Wafer Breakage
Do Not Vacuum Bag Shipper

CAUTION
WAFFER SENSITIVE TO
TEMPERATURE DURING STORAGE
WAFFER MAY BE DAMAGED AND
WARRANTY VOIDED BY STORING
OUTSIDE OF RECOMMENDED
RANGE
STORE WAFFER BETWEEN
15°C (59°F) TO 40°C (104°F) AT ALL
TIMES. SEE OWNER'S MANUAL.



10-40000-0000-00



KLA 
SensArray Division

RESET

NOTICE

WAFER BREAKAGE HAZARD

Vacuum Bagging May Cause
Wafer Breakage


Do Not Vacuum Bag Shipper

CAUTION

WAFER SENSITIVE TO
TEMPERATURE DURING STORAGE

WAFER MAY BE DAMAGED AND
WARRANTY VOIDED BY STORING
OUTSIDE OF RECOMMENDED
RANGE

STORE WAFER BETWEEN
15C (59F) TO 40C (104F) AT ALL
TIMES. SEE OWNER'S MANUAL.



0548685-000 AD

KLA 
SensArray Division

