

Ole Myrtue

January 29, 2004

Changes in QTKRH-36

RF

The antenna has been re-tuned for better matching.

BB

Some resistor changes related to the internal power regulator and LED drivers

Mechanics

No changes.

Other

Second source VCO in PLL – electrically identical, no changes to matching component.

Results of internal review (FCC focus)

Radiated power output, Field strength of spurious radiation, RF Exposure